

PUGET SOUND AIR POLLUTION CONTROL AGENCY
KING COUNTY ▲ KITSAP COUNTY ▲ PIERCE COUNTY ▲ SNOHOMISH COUNTY

February 27, 1996

RECEIVED

FEB 28 1996

AGCW-SEATTLE

Reg. No. 11339

Gerry Brown
Ash Grove Cement Co.
3801 E Marginal Way S
Seattle, WA 98134

Dear Mr. Brown:

Notice of Violation No. 34406

This is to acknowledge your request for a meeting to discuss the above referenced Notice of Violation. A meeting has been scheduled **at your facility** on March 20, 1996, at 3:00 p.m.

If this date and time is not acceptable to you, please contact me at 689-4056 or Connie Cox at 689-4095.

Sincerely,

Melissa McAfee
Air Pollution Inspector

cc: Rosemary Busterna, PSAPCA
Elizabeth Gilpin, PSAPCA
Fred Austin, PSAPCA
Jim Nolan, PSAPCA

MM/cbc

Dennis J. McLerran, Air Pollution Control Officer

B O A R D O F D I R E C T O R S

AGCS2M001016

Chairman: Win Granlund, Commissioner, Kitsap County
Janet Chalupnik, Member at Large
Edward D. Hansen, Mayor, Everett

Lynn S. Horton, Mayor, Bremerton
R.C. Johnson, Councilman, Snohomish County
Gary Locke, King County Executive

Harold G. Moss, Mayor, Tacoma
Norman B. Rice, Mayor, Seattle
Doug Sutherland, Pierce County Executive

FEB 21 1996

PUGET SOUND AIR POLLUTION CONTROL AGENCY

110 Union Street, Suite 500, Seattle, Washington 98101-2038

206-343-8800 / 1-800-552-3565 / Fax 206-343-7522

Registration No. 11339
Cert. Mail No. 2035473342

No. 34406

NOTICE OF VIOLATION

Date of Violation: Feb 9th, 19 96 at 10:30 A.m.

Name <u>Ash Grove Cement Co.</u>		Responsible Person, Title <u>Gerry Brown Env./Safety Manager</u>	
Location of Violation (Address) <u>3801 E Marginal Wy So.</u>		City <u>Seattle</u>	Zip <u>98134</u>
Mailing Address <u>as above</u>		City, State <u>Seattle, WA</u>	Phone <u>(206) 623-5596</u>

DID UNLAWFULLY CAUSE OR ALLOW VIOLATION OF:

REGULATION I OF THE PUGET SOUND AIR POLLUTION CONTROL AGENCY FOR:

- ☐ Section 5.05(e) Failure to develop and implement an operation and maintenance plan.
☐ Section 6.03(a) Failure to obtain Notice of Construction approval prior to construction/installation/establishment of a source.
☒ Section 6.09(b) Failure to meet conditions of an Order of Approval.
☐ Section 9.03(a) Visible emissions in excess of 20% opacity for periods aggregating more than 3 minutes/hour.
☐ Section 9.04 Particulate matter deposited in quantities/characteristics/duration so as to be injurious or interfere with enjoyment of life/property.
☐ Section 9.11(a) Emission of air contaminant in quantities/characteristics/duration so as to be injurious or interfere with enjoyment of life/property.
☐ Section 9.12(b) Emission of odor-bearing air contaminants without use of best available control technology.
☐ Section 9.15(a) Emission of fugitive dust without use of best available control technology.
☒ Section 9.15(b) Operation of vehicle on paved public roadway with dirt/mud/debris on undercarriage (track out) or load spillage.
☒ Section 9.15(c) Emission of fugitive dust from manufacturing process equipment or control apparatus.
☐ Section 9.16 Failure to apply VOC-containing material using spray equipment in an enclosed area with filtered exhaust and vertical stack.
☐ Section 9.20 Failure to operate and maintain equipment in good working order.

☐ Section _____


☐ Section _____

FACTS ALLEGED TO CONSTITUTE A VIOLATION Causing or allowing fugitive dust emissions from the mid point of the conveyor between the 6-cooler and the six pack and for allowing heavy fugitive dust from the underside of the conveyor ~ 10 ft. so. of the storage shed at 3801 E Marginal Wy So. in Seattle.


CORRECTIVE ACTION ORDER

Under the provisions of Section 3.09 of Regulation I and RCW 70.94.211 you are ordered to submit a written report within ten (10) days of receipt of this Notice describing the necessary corrective action you have taken or propose to take, including a schedule, to achieve continuous compliance with the regulations, and take the following necessary corrective action:

Issued By



Date/Time

2/20/96


Received By

Signing this Notice is not an admission of guilt

Form No. 70-119 (Revised 9/93)

AGCS2M001017